



CONSTRUCTION EQUIPMENT

24467 VOLVO A30G 753393 - FRONT AXLE



Sample No: VCP429003
Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102
Job No: 24467



218 - ASCENDUM MACHINERY INC - N. CHARLESTON
 7235 CROSS COUNTRY RD.
 NORTH CHARLESTON, SC
 US 29418
 Contact: MATT MITCHAM
 matt.mitcham@ascendummachinery.com
 T:
 F: (843)414-1129

SAMPLE INFORMATION

Sample Number	VCP429003	---	---	---
Sample Date	21 Nov 2023	---	---	---
Machine Hours	590	---	---	---
Oil Hours	500	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

OIL CONDITION

Visc @ 40°C	cSt	█ 103	---	---	---
-------------	-----	-------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 2	---	---	---

WEAR METALS

Iron	ppm	█ 218	---	---	---
Copper	ppm	█ 14	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 6	---	---	---
Molybdenum	ppm	█ 6	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 14	---	---	---
Vanadium	ppm	<1	---	---	---

ADDITIVES

Calcium	ppm	█ 217	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 101	---	---	---
Phosphorus	ppm	█ 1445	---	---	---
Barium	ppm	█ 5	---	---	---
Boron	ppm	█ 287	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO3387
Unique No: 10763020
Signed: Don Baldrige
Report Date: 30 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

