

CONSTRUCTION EQUIPMENT VOLVO A45G 353267 - HYDRAULIC SYSTEM



Sample No: VCP422049

Oil Type: VOLVO SUPER HYDRAULIC OIL 46

Job No:

VOLVO				
SAMPLE IN	NFORMATION			
Sample Number	-	VCP422049	VCP423305	
Sample Date		24 Nov 2023	10 Jul 2023	
Machine Hours		2400	1257	
Oil Hours		0	0	
Oil Changed		Not Changd	Not Changd	
Sample Status		NORMAL	ATTENTION	
AOTAO UII CUNDI.	TION			
OIL CONDI	-			
Visc @ 40°C	cSt	44.0	43.5	
Acid Number (AN)	mg KOH/g	■ 0.35	■ 0.41	
CONTAMIN	NATION			
Water	%	NEG	NEG	
	%			
Particles > 4µm		5948 □ 442	9721 □ 3218	
Particles > 6µm			_	
Particles >14µm		14	▲ 174	
ISO 4406:1999 (c)		20/16/11	20/19/15	
Silicon	ppm	■ 16	8	
Sodium	ppm	0	<1	
Potassium	ppm	2	<u> </u>	
VOLVO				
WEAR ME	TALS			
Iron	ppm	12	6	
Copper	ppm	4	2	
Lead	ppm	3	= <1	
Tin	ppm	■<1	1 0	
Aluminum	ppm	<u> </u>	■3	
Chromium	ppm	1	- <1	
Molybdenum	ppm	1 <1	= <1	
Nickel	ppm	■<1	0	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm		- <1	
Vanadium	ppm	0	0	
ADDITIVE	7			
ADDITIVE	7			
Calcium	ppm	73	7 9	
Magnesium	ppm	2	0	
Zinc	ppm	482	465	
Phosphorus	ppm	369	■344	
Barium	ppm	■ <1	0	
Boron	ppm	■ 0	0	



LEE MAR BUILDING & CONSTRUCTION

15685 PINE RIDGE ROAD FORT MYERS, FL US 33908-2626 Contact: JUDY GIBSON jgibson13@earthlink.net T: (239)481-2613 F: (239)481-9354

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:LEEFORUnique No:10764110Signed:Wes DavisReport Date:29 Nov 2023



CONSTRUCTION EQUIPMENT





GRAPHS

