

## CONSTRUCTION EQUIPMENT 565 VOLVO EC480EL 315228 - RIGHT SWING DRIVE



Sample No: VCP412791

Oil Type: MOBIL MOBILUBE HD 85W140

**Job No:** 565

VOLVO	INFORMATIO	V		
	INFORMATIO			
Sample Number		VCP412791	 	
Sample Date		20 Nov 2023	 	
Machine Hours		465	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	NITION			
		,	 	
Visc @ 40°C	cSt	<b>146</b>	 	
VOLVO				
CONTAM	IINATION			
Water	%	NEG	 	
Silicon	ppm	<b>17</b>	 	
Sodium	ppm	<b>2</b>	 	
Potassium	ppm	<b>■</b> 0	 	
VOLVO				
WEAR M	ETALS			
Iron	ppm	<b>7</b> 4	 	
Copper	ppm	<b>26</b>	 	
Lead	ppm	<b>0</b>	 	
Tin		<b>0</b>	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	1	 	
	ppm	_	 	
Molybdenum	ppm	0		
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b>3</b>	 	
Vanadium	ppm	<1	 	
VOLVO				
<b>ADDITIV</b>	ES			
Calcium		<b>6</b> 4	 	
Magnesium	ppm	<b>■</b> 64	 	
Zinc	ppm	<b>■</b> 24	 	
Phosphorus	ppm	<b>2</b> 97	 	
•	ppm			
Barium	ppm	0	 	
Boron	ppm	<b>■</b> 1	 	



VCES- VOLVO CONSTRUCTION EQUIPMENT
12345 MAPLEVIEW STREET
LAKESIDE, CA
US 92040
Contact: Mark Stewart
mark.stewart@vcesvolvo.com

T: X: F: X:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. Confirm oil type. The condition of the oil is acceptable for the time in service.

Depot:VOLVO4488Unique No:10764304Signed:Don BaldridgeReport Date:01 Dec 2023



## **CONSTRUCTION EQUIPMENT**





