## CONSTRUCTION EQUIPMENT S50801324 IDEAL TRAC VOLVO L220H 2735 - FRONT AXLE



## VCP441937 Sample No:

VOLVO

Oil Type:	VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102
Job No:	S50801324 IDEAL TRAC

NEG

33

0 🔲

## SAMPLE INFORMATION

**OIL CONDI** 

CONTAMI

%

ppm

ppm

Sample Number Sample Date

Machine Hours **Oil Hours** Oil Changed Sample Status

Visc @ 40°C

Water

Silicon

Sodium

inf ukma i iun			
	VCP441937	 	
	22 Nov 2023	 	 VCES- VOLVO CONSTRUCTION EQUIPMENT
	10232	 	 8594 FRUITRIDGE ROAD
	0	 	 SACRAMENTO, CA
	Changed	 	 US 95826
	NORMAL	 	 Contact: RAY KRANZUSCH
			ray.kranzusch@vcesvolvo.com
DITION			T:
			F:
cSt	<b>43.0</b>	 	
			Diagnosis
INATION			
			Resample at the next service interval

sample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Potassium	ppm	3							
WEAR METALS									
Iron	ppm	<b>190</b>							
Copper	ppm	86							
Lead	ppm	□<1							
Tin	ppm								
Aluminum	ppm	2							
Chromium	ppm	2							
Molybdenum	ppm	<b>1</b>							
Nickel	ppm	2							
Titanium	ppm	<1							
Silver	ppm	<1							
Manganese	ppm	3							
Vanadium	ppm	0							

OLVO **ADDITIVES** Calcium 3914 ppm Magnesium **16** ppm Zinc ppm 1673 Phosphorus ppm 1123 Barium ppm 0 🔲 128 Boron ppm


> Depot: VOLVO4485 Unique No: 10764551 Signed: Wes Davis Report Date: 29 Nov 2023

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO4485 [WUSCAR] 06020051 (Generated: 11/29/2023 17:46:51) Rev: 1

Contact/Location: RAY KRANZUSCH - VOLVO4485