

CONSTRUCTION EQUIPMENT SPM633152 MAJOR VOLVO L110H 6

VOLVO L 1 1 0 H 6 3 2 3 7 7 - FRONT AXLE

Sample No: VCP428544

Oil Type: **VOLVO WET BRAKE TRANSAXLE OIL**

Job No: SPM633152 MAJOR

VOLVO	LINEODMATIO	.		
	E INFORMATIO	N		
Sample Number		VCP428544	 	
Sample Date		08 Nov 2023	 	
Machine Hours		2237	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	IDITION			
Visc @ 40°C	cSt	■40.2	 	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	 	
Silicon	ppm	■23	 	
Sodium	ppm	13	 	
Potassium	ppm	1	 	
	РРШ			
VOLVO				
WEAR N	METALS			
Iron	ppm	<u></u> 547	 	
Copper	ppm	2	 	
Lead	ppm	■<1	 	
Tin	ppm	-< 1	 	
Aluminum	ppm	1	 	
Chromium	ppm	10	 	
Molybdenum	ppm	15	 	
Nickel	ppm	2	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	16	 	
Vanadium	ppm	<1	 	
ADDITIV	VES			
Calcium	ppm	■3769	 	
Magnesium	ppm	1 3	 	
Zinc	ppm	1493	 	
Phosphorus	ppm	1281	 	
Barium	ppm	0	 	
Boron	ppm	128	 	



ALTA CONSTRUCTION EQUIPMENT LLC

G-3283 S. DORT HIGHWAY BURTON, MI US 48529 Contact: BURTON SERVICE BURTON.SERVICE@ALTAEQUIPMENT.COM

T: F:

Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO5023 **Unique No:** 10765251 Signed: Don Baldridge Report Date: 03 Dec 2023



CONSTRUCTION EQUIPMENT





