

## CONSTRUCTION EQUIPMENT 1316 IAA VOLVO L90G 3186 - FRONT AXLE



Sample No: VCP441936
Oil Type: VOLVO WB 102

**Job No:** 1316 IAA

SAMPLE	E INFORMATION			
Sample Number	_	VCP441936	 	
Sample Date		20 Nov 2023	 	
Machine Hours		16494	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	IDITION			
Visc @ 40°C	cSt	<b>□</b> 39.4	 	
VISC @ 40 C	CSL	<b>39.4</b>	 	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>11</b>	 	
Sodium	ppm	<b>8</b>	 	
Potassium	ppm	<1	 	
VOLVO	AETAL C			
WEAR N	METAL2			
Iron	ppm	<b>11</b>	 	
Copper	ppm	<b>■&lt;1</b>	 	
Lead	ppm	<b></b>	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b></b>	 	
Nickel	ppm	<b>■</b> 0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b></b>	 	
Vanadium	ppm	<1	 	
ADDITIV	VES			
Calcium	ppm	<b>□</b> 3790	 	
Magnesium	ppm	<b>■13</b>	 	
Zinc	ppm	<b>1571</b>	 	
Phosphorus	ppm	<b>1282</b>	 	
Barium	ppm	<b>0</b>	 	
Boron	ppm	<b>130</b>	 	
20.011	PPIII			



VCES- VOLVO CONSTRUCTION EQUIPMENT 8594 FRUITRIDGE ROAD SACRAMENTO, CA US 95826 Contact: RAY KRANZUSCH ray.kranzusch@vcesvolvo.com T:

F:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO4485Unique No:10765263Signed:Wes DavisReport Date:30 Nov 2023



## **CONSTRUCTION EQUIPMENT**





