

CONSTRUCTION EQUIPMENT 622085 VOLVO A40G 352851 - FRONT AXLE



Sample No: VCP429372

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 622085

SAMPLE	INFORMATION				
Sample Number		VCP429372	VCP420262	VCP385546	VCP362326
Sample Date		06 Nov 2023	12 Apr 2023	07 Oct 2022	17 Mar 2022
Machine Hours		4099	3090	2036	1095
Oil Hours		3000	2090	1500	1095
Oil Changed		Changed	Not Changd	Not Changd	Changed
Sample Status		ATTENTION	ATTENTION	NORMAL	NORMAL
OIL CON	DITION				
Visc @ 40°C	cSt	<u>▲</u> 54.6	<u>▲</u> 55.9	□ 55.3	43.7
VISC @ 40 C	CSL	A 34.0	55.9	55.5	43.7
VOLVO					
CONTAN	INATION				
Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	1	■ 3	3
Sodium	ppm	1	1	0	1
Potassium	ppm	■3	- <1	2	■3
WEAR M	IETALS				
Iron	ppm	□ 181	■ 142	115	□176
Copper	ppm	1	- <1	1	<1
Lead	ppm	O	0	0	1 0
Tin	ppm	_ <1	0	<u> </u>	- <1
Aluminum	ppm	■ <1	- <1	- <1	 <1
Chromium	ppm	2	2	2	2
Molybdenum	ppm	1	2	1	2
Nickel	ppm	■ <1	- <1	□ 0	 <1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	5	5	4	■8
Vanadium	ppm	<1	0	<1	0
ADDITIV	/ES				
Calcium	ppm	10	3 7	<u>47</u>	1 6
Magnesium	ppm	■ <1	1	2	0
Zinc	ppm	10	2 7	□29	1 2
Phosphorus	ppm	2158	2386	2403	2 403
Barium	ppm	0	0	0	<u> </u>
Boron	ppm	148	266	□265	□256



RIPA AND ASSOCIATES

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T·

Diagnosis

F:

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot:RIPTAMUnique No:10765287Signed:Don BaldridgeReport Date:03 Dec 2023



CONSTRUCTION EQUIPMENT





