



# CONSTRUCTION EQUIPMENT

633991 MOSAIC VOLVO L220H 3205 - COOLANT



**Sample No:** VCP429225  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 633991 MOSAIC



## SAMPLE INFORMATION

Sample Number	VCP429225	---	---	---
Sample Date	17 Nov 2023	---	---	---
Machine Hours	6388	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## COOLANT CONDITION

pH	Scale 0-14	■ 7.13	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 46.7	---	---	---
Freezing Point	°C	■ -26	---	---	---

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Orange	---	---	---

**Depot:** VOLVO0093  
**Unique No:** 10765404  
**Signed:** Jonathan Hester  
**Report Date:** 04 Dec 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

