



# CONSTRUCTION EQUIPMENT

633392 TUCKER VOLVO L110H 631215 - COOLANT



**Sample No:** VCP429374  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** 633392 TUCKER



## SAMPLE INFORMATION

Sample Number	<b>VCP429374</b>	VCP278847	---	---
Sample Date	<b>09 Nov 2023</b>	23 Nov 2020	---	---
Machine Hours	<b>12508</b>	6905	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## COOLANT CONDITION

pH	Scale 0-14	<b>7.49</b>	7.29	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>NT</b>	NT	---	---
Percentage Glycol	%	<b>51.3</b>	52	---	---
Freezing Point	°C	<b>-38</b>	-42	---	---

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	<b>normal</b>	normal	---	---
Coolant Color	<b>Orange</b>	Yllow	---	---

**Depot:** VOLVO0093  
**Unique No:** 10765405  
**Signed:** Jonathan Hester  
**Report Date:** 04 Dec 2023



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity



### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

