

CONSTRUCTION EQUIPMENT X58917 VOLVO L120H 633249 - HYDRAULIC SYSTEM



Sample No: VCP425339

Oil Type: AW HYDRAULIC OIL ISO 46

Job No: X58917

VOLVO	INFORMATION				
	INFURMATION				
Sample Number		VCP425339			
Sample Date		27 Nov 2023			
Machine Hours		2012			
Oil Hours		0			
Oil Changed		Not Changd			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	41.6			
Acid Number (AN		0.51			
Acid Hamber (Air	ing Konyg	 0.3 i			
VOLVO	WILD TION				
CONTAM	1INATION				
Water	%	NEG			
Particles >4µm		11360			
Particles >6µm		■ 588			
Particles > 14µm		■ 51			
ISO 4406:1999 (c))	21/16/13			
Silicon	ppm	2			
Sodium	ppm	0			
Potassium	ppm	2			
WEAR M	IETALS				
Iron	ppm	12			
Copper	ppm	<u> </u>			
Lead	ppm	<u> </u>			
Tin	ppm	 0			
Aluminum	ppm	1			
Chromium	ppm	4			
Molybdenum	ppm				
Nickel	ppm	■ 0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	0			
Vanadium	ppm	0			
ADDITIV	IES				
Calcium		6 1			
Magnesium	ppm	1 7			
Zinc	ppm	397			
Phosphorus	ppm	305			
Barium		0			
-	ppm	U			



SCOTT EQUIPMENT COMPANY LLC - Saint Rose

PO BOX 997 SAINT ROSE, LA US 70087 Contact: DENISE CORVERS dcorvers@scottcompanies.com T: (504)461-0961

F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:SCOSAIUnique No:10766019Signed:Wes DavisReport Date:01 Dec 2023

Boron



CONSTRUCTION EQUIPMENT





GRAPHS

