



# CONSTRUCTION EQUIPMENT

## VOLVO MCT135C 1640446 - DIESEL FUEL



**Sample No:** VCP430842  
**Oil Type:** NOT GIVEN  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP430842	---	---	---
Sample Date	27 Nov 2023	---	---	---
Machine Hours	3204	---	---	---
Sample Status	NORMAL	---	---	---

### ALTA EQUIPMENT

5985 COURT STREET ROAD  
 SYRACUSE, NY  
 US 13206

Contact: JIM STRIGLE  
 JIM.STRIGLE@ALTG.COM  
 T: (315)437-2611  
 F: (315)434-9471



### FUEL CONDITION

Sulfur	ppm	0	---	---	---
Visc @ 40°C	cSt	2.07	---	---	---



### CONTAMINATION

Water	%	0.003	---	---	---
Lead	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Aluminum	ppm	1	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	< 1	---	---	---

### Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time. All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

**Depot:** VOLVO0142  
**Unique No:** 10766418  
**Signed:** Jonathan Hester  
**Report Date:** 04 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

Pensky-Martens Flash Point (°C)

