CONSTRUCTION EQUIPMENT G08058 VOLVO EC350 310866 - HYDRAULIC SYSTEM

 Sample No:
 VCP435005

 Oil Type:
 NOT GIVEN

 Job No:
 G08058

VOLVO

## SAMPLE INFORMATION

Sample Number	-	VCP435005	 	
Sample Date		27 Nov 2023	 	
Machine Hours		5172	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDIT	LION			
Visc @ 40°C	cSt	42.5	 	
Acid Number (AN)	mg KOH/g	0.33	 	
CONTAMIN	IATION			
Water	%	NEG	 	
Particles >4µm		<b>19052</b>	 	
Particles >6µm		637	 	
D (1) 14		- 40		

Particles >6µm		637	 	
Particles >14µm		<b>16</b>	 	
ISO 4406:1999 (c)		21/16/11	 	
Silicon	ppm	3	 	
Sodium	ppm	2	 	
Potassium	ppm	0	 	

## 🎾 WEAR METALS

Iron	ppm	3	 	
Copper	ppm	<b>4</b> 3	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	
Chromium	ppm	<b></b> <1	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	0	 	
Vanadium	ppm	<1	 	

VOLVO

Calcium	ppm	24			
Magnesium	ppm	0			
Zinc	ppm	263			
Phosphorus	ppm	318			
Barium	ppm	0			
Boron	ppm	0			



#### **HOFFMAN EQUIPMENT - DEPTFORD**

1330 HURFFVILLE ROAD DEPTFORD, NJ US 08096 Contact: TAMMY SANDORA tammy.sandora@hoffmanequip.com T: (856)227-6400 F: (856)227-0046

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO8880

 Unique No:
 10766940

 Signed:
 Wes Davis


 Report Date:
 04 Dec 2023

# **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Contact/Location: TAMMY SANDORA - VOLVO8880