



# CONSTRUCTION EQUIPMENT

## 24465 VOLVO A25 752380 - TRANSMISSION



**Sample No:** VCP429029  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 24465



**218 - ASCENDUM MACHINERY INC - N. CHARLESTON**  
 7235 CROSS COUNTRY RD.  
 NORTH CHARLESTON, SC  
 US 29418  
 Contact: MATT MITCHAM  
 matt.mitcham@ascendummachinery.com  
 T:  
 F: (843)414-1129



### SAMPLE INFORMATION

Sample Number	VCP429029	---	---	---
Sample Date	28 Nov 2023	---	---	---
Machine Hours	2179	---	---	---
Oil Hours	1000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



### OIL CONDITION

Visc @ 40°C	cSt	█ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 16	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 5	---	---	---



### WEAR METALS

Iron	ppm	█ 54	---	---	---
Copper	ppm	█ 29	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 5	---	---	---
Aluminum	ppm	█ 32	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 72	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 5	---	---	---
Phosphorus	ppm	█ 199	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 69	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO3387  
**Unique No:** 10767340  
**Signed:** Sean Felton  
**Report Date:** 05 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

