



CONSTRUCTION EQUIPMENT

RSO-036291 VOLVO ECR88D 217195 - DIESEL FUEL



Sample No: VCP428827
Oil Type: NOT GIVEN
Job No: RSO-036291



SAMPLE INFORMATION

Sample Number	VCP428827	---	---	---
Sample Date	29 Nov 2023	---	---	---
Machine Hours	808	---	---	---
Sample Status	NORMAL	---	---	---



FUEL CONDITION

Sulfur	ppm	0	---	---	---
Visc @ 40°C	cSt	2.31	---	---	---



CONTAMINATION

Water	%	0.004	---	---	---
Lead	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Aluminum	ppm	2	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	0	---	---	---

COWIN EQUIPMENT COMPANY

2238 PINSON VALLEY PARKWAY
BIRMINGHAM, AL
US 35217

Contact: BRANTLY CLAY
bclay@cowin.com

T:
F: (205)856-2106

Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time. All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot: VOLVO8528
Unique No: 10767372
Signed: Jonathan Hester
Report Date: 05 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

