



CONSTRUCTION EQUIPMENT

G08058 VOLVO EC350 310866 - COOLANT



Sample No: VCP435006
Oil Type: NOT GIVEN
Job No: G08058



SAMPLE INFORMATION

Sample Number	VCP435006	---	---	---
Sample Date	27 Nov 2023	---	---	---
Machine Hours	5172	---	---	---
Sample Status	NORMAL	---	---	---

HOFFMAN EQUIPMENT - DEPTFORD
1330 HURFFVILLE ROAD
DEPTFORD, NJ
US 08096
Contact: TAMMY SANDORA
tammy.sandora@hoffmanequip.com
T: (856)227-6400
F: (856)227-0046



COOLANT CONDITION

pH	Scale 0-14	■ 7.52	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 37.5	---	---	---
Freezing Point	°C	■ -7	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO8880
Unique No: 10767376
Signed: Jonathan Hester
Report Date: 05 Dec 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

