**CONSTRUCTION EQUIPMENT** 40809 VOLVO SD115B 236995 - DIESEL FUEL



 Sample No:
 VCP433698

 Oil Type:
 NOT GIVEN

 Job No:
 40809

VOLVO

VOLVO				
	NFORMATIC	N		
Sample Number		VCP433698	 	
Sample Date		01 Dec 2023	 	
Machine Hours		658	 	
Sample Status		NORMAL	 	
FUEL CON			 	
Sulfur	ppm	<b></b> <1	 	
Visc @ 40°C	cSt	2.24	 	
CONTAMI				
	NATION			
Water	%	0.004	 	
Lead	ppm	0	 	
Nickel	ppm	0	 	
Aluminum	ppm	0	 	
Vanadium	ppm	0	 	
Silicon	ppm	0	 	

## 215 - ASCENDUM MACHINERY INC - CAYCE

2303 AIRPORT BLVD CAYCE, SC US 29033 Contact: GARY MARTIN GARY.MARTIN@ASCENDUMMACHINERY.COM T: (803)727-9615 F: (803)791-9920

## Diagnosis

This is a baseline read-out on the submitted sample. No corrective action is recommended at this time.All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

 Depot:
 VOLVO0013

 Unique No:
 10768708

 Signed:
 Jonathan Hester

 Report Date:
 06 Dec 2023



VOLVO

GRAPHS



## Pensky-Martens Flash Point (°C)

				-	empe	clature	د				
	10	-8	-6	-4	-2	0	2	4	6	8	10.
		ļ	ļ	ļ	ļ	ļ	ļ	ļ	ļ	ļ	-
Dec1/23 -			i	1	i		į	i		1	
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
	_										_
Dec1/23.			1		Ì		j	1		1	-