



CONSTRUCTION EQUIPMENT

X10692 VOLVO EC300DL 210381 - COOLANT



Sample No: VCP413424
Oil Type: EXTENDED LIFE COOLANT
Job No: X10692



SAMPLE INFORMATION

Sample Number	VCP413424	---	---	---
Sample Date	21 Nov 2023	---	---	---
Machine Hours	6419	---	---	---
Sample Status	NORMAL	---	---	---

SCOTT EQUIPMENT COMPANY LLC - Texarkana
 5401 SANDERSON LANE
 TEXARKANA, AR
 US 71854
 Contact: JAMES DOSS
 jdoss@scottcompanies.com
 T:
 F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.97	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.5	---	---	---
Freezing Point	°C	■ -33	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

Depot: VOLVO1034
Unique No: 10768724
Signed: Jonathan Hester
Report Date: 06 Dec 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

