CONSTRUCTION EQUIPMENT RYAN GOLF VOLVO EC480 314824 - HYDRAULIC SYSTEM

Sample No:VCP432073Oil Type:VOLVO SUPER HYDRAULIC OIL 46

VOLVO

Job No:

RYAN GOLF

SAMPLE INFORMATION

Sample Number	-	VCP432073	VCP375974			
Sample Date		05 Dec 2023	06 Aug 2022			
Machine Hours		0	653			
Oil Hours		0	1500			
Oil Changed		Not Changd	Not Changd			
Sample Status		ABNORMAL	ABNORMAL			
OIL CONDITION						
Visc @ 40°C	cSt	41.5	42.7			
Acid Number (AN)	mg KOH/g	0.42	0.48			

%	NEG	NEG		
	<u> </u>	▲ 100579		
	6 55539	<u> </u>		
	397	764		
	25/23/16	24/22/17		
ppm	8	5		
ppm	∎1	0		
ppm	0	0		
	ppm ppm	 ▲ 160111 ▲ 55539 ■ 397 25/23/16 ppm ■ 8 ppm ■ 1 	▲ 160111 ▲ 100579 ▲ 55539 ▲ 24227 ■ 397 ■ 764 25/23/16 24/22/17 ppm ■ 8 ■ 5 ppm ■ 1 ■ 0	▲ 160111 ▲ 100579 ▲ 55539 ▲ 24227 ■ 397 ■ 764 25/23/16 24/22/17 ppm ■ 8 ■ 5 ppm ■ 1 ■ 0

🎾 WEAR METALS

ppm	1	2		
ppm	37	19		
ppm	0	 < 1		
ppm	0	<1		
ppm	□<1	1		
ppm		0		
ppm	0	 < 1		
ppm	0	□ <1		
ppm	0	0		
ppm	0	<1		
ppm	□<1	0		
ppm	0	0		
	ppm ppm ppm ppm ppm ppm ppm ppm ppm ppm	ppm 1 ppm 37 ppm 0 ppm 0 ppm <1	ppm 1 2 ppm 37 19 ppm 0 <1	ppm 1 2 ppm 37 19 ppm 0 <1

VOLVO

Calcium	ppm	39	99		
Magnesium	ppm	0	0		
Zinc	ppm	394	542		
Phosphorus	ppm	379	425		
Barium	ppm	0	0		
Boron	ppm	0	<1		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD

TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

We recommend you service the filters on this component. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

 Depot:
 VOLVO0093

 Unique No:
 10776126

 Signed:
 Wes Davis


 Report Date:
 07 Dec 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06026335 (Generated: 12/07/2023 15:32:12) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093