



CONSTRUCTION EQUIPMENT

HERC RENTALS VOLVO A30G 753512 - BOGIE/CENTER AXLE



Sample No: VCP436179
Oil Type: NOT GIVEN
Job No: HERC RENTALS



SAMPLE INFORMATION

Sample Number	VCP436179	---	---	---
Sample Date	14 Oct 2023	---	---	---
Machine Hours	702	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█ 101	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 4	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 265	---	---	---
Copper	ppm	█ 12	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 6	---	---	---
Molybdenum	ppm	12	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	15	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	172	---	---	---
Magnesium	ppm	0	---	---	---
Zinc	ppm	75	---	---	---
Phosphorus	ppm	1371	---	---	---
Barium	ppm	3	---	---	---
Boron	ppm	303	---	---	---

Depot: VOLVO0093
Unique No: 10776629
Signed: Jonathan Hester
Report Date: 08 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

