



CONSTRUCTION EQUIPMENT

GEHREAL RV VOLVO L20H 220368 - REAR AXLE



Sample No: VCP432299
Oil Type: NOT GIVEN
Job No: GEHREAL RV



SAMPLE INFORMATION

Sample Number	VCP432299	---	---	---
Sample Date	31 Oct 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: JOHN FARDELLA
 john.fardella@altg.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█ 62.1	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 25	---	---	---
Sodium	ppm	█ 16	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 164	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	10	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	3436	---	---	---
Magnesium	ppm	11	---	---	---
Zinc	ppm	1378	---	---	---
Phosphorus	ppm	1115	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	111	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10776630
Signed: Jonathan Hester
Report Date: 08 Dec 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

