



# CONSTRUCTION EQUIPMENT

HERC RENTALS VOLVO A30G 753512 - TRANSMISSION (AUTO)



**Sample No:** VCP436184  
**Oil Type:** DEXRON III  
**Job No:** HERC RENTALS



## SAMPLE INFORMATION

Sample Number	VCP436184	---	---	---
Sample Date	14 Oct 2023	---	---	---
Machine Hours	702	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC  
8418 PALM RIVER ROAD  
TAMPA, FL  
US 33619  
Contact: KENNY HANEY  
khaney@flaglerce.com  
T: (813)630-0077  
F: (813)630-2233



## OIL CONDITION

Visc @ 40°C	cSt	█ 28.6	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	█ 0.083	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 3	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 24	---	---	---
Copper	ppm	█ 18	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 14	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	█ 0	---	---	---



## ADDITIVES

Calcium	ppm	█ 72	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 189	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 77	---	---	---

**Depot:** VOLVO0093  
**Unique No:** 10776686  
**Signed:** Jonathan Hester  
**Report Date:** 08 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

