

Sample No: VCP408591

Oil Type: NOT GIVEN

Job No: SPM634853-10

SAMPLE	INFORMATION	N		
Sample Number		VCP408591	 	
Sample Date		30 Nov 2023	 	
Machine Hours		0	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
Sample Status		NORIVIAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>49.7</b>	 	
VOLVO				
LONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>-&lt;1</b>	 	
Potassium	ppm	<b>3</b>	 	
VOLVO	AFTALC			
WEAR N	JE I ALS			
Iron	ppm	■300	 	
Copper	ppm	<b>5</b>	 	
Lead	ppm	<b>■&lt;1</b>	 	
Tin	ppm	<b>0</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■</b> 4	 	
Molybdenum	ppm	6	 	
Nickel	ppm	<b>2</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	18	 	
Vanadium	ppm	0	 	
VOLVO	IEC			
ADDITIV	172			
Calcium	ppm	9	 	
Magnesium	ppm	0	 	
Zinc	ppm	5	 	
Phosphorus	ppm	2446	 	
Barium	ppm	0	 	
Boron	ppm	226	 	



## **ALTA EQUIPMENT COMPANY**

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T:

F: (239)481-3302

## Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0090Unique No:10777037Signed:Don BaldridgeReport Date:08 Dec 2023



## **CONSTRUCTION EQUIPMENT**





