**CONSTRUCTION EQUIPMENT** LKQ VOLVO L60H 622998 - HYDRAULIC SYSTEM



**Sample No:** VCP440777

ZOLV

Oil Type:	DIESEL ENGINE OIL SAE 15W40
Job No:	LKQ

SAMPLE IN	NFORMATION				
Sample Number		VCP440777			
Sample Date		23 Nov 2023			
Machine Hours		1027			
Oil Hours		0			
Oil Changed		N/A			
Sample Status		ABNORMAL			
OIL CONDI	TION				
Visc @ 40°C	cSt	<b>47.1</b>			
Acid Number (AN)	mg KOH/g	0.37			

Water	%	NEG	 	
Particles >4µm		65544	 	
Particles >6µm		🔺 19967	 	
Particles >14µm		<b>A</b> 1170	 	
ISO 4406:1999 (c)		23/21/17	 	
Silicon	ppm	3	 	
Sodium	ppm	0	 	
Potassium	ppm	<b></b> <1	 	



VOLVO

ADDITIN	/ES			
Calcium	ppm	67	 	
Magnesium	ppm	8	 	
Zinc	ppm	361	 	
Phosphorus	ppm	286	 	
Barium	ppm	0	 	
Boron	ppm	0	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

We recommend you service the filters on this component. Resample at the next service interval to monitor.All component wear rates are normal. There is a high amount of particulates present in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type. The AN level is acceptable for this fluid.

 Depot:
 VOLVO0093

 Unique No:
 10777451

 Signed:
 Don Baldridge


 Report Date:
 08 Dec 2023

## **CONSTRUCTION EQUIPMENT**



## GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06027660 (Generated: 12/09/2023 11:25:48) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093