



CONSTRUCTION EQUIPMENT

VOLVO L60H 622388 - REAR AXLE



Sample No: VCP0007944

Oil Type: NOT GIVEN

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007944	---	---	---
Sample Date	05 Dec 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: TECHNICIAN ACCOUNT
catherine.anastasio@wearcheck.com
T:
F: (904)737-1260



OIL CONDITION

Visc @ 40°C	cSt	■ 39.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 15	---	---	---
Sodium	ppm	■ 13	---	---	---
Potassium	ppm	■ 6	---	---	---



WEAR METALS

Iron	ppm	■ 279	---	---	---
Copper	ppm	■ 2	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ 8	---	---	---
Molybdenum	ppm	5	---	---	---
Nickel	ppm	■ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	13	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	3664	---	---	---
Magnesium	ppm	7	---	---	---
Zinc	ppm	1521	---	---	---
Phosphorus	ppm	1274	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	119	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0092
Unique No: 10777942
Signed: Don Baldrige
Report Date: 10 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

