

CONSTRUCTION EQUIPMENT 24534 VOLVO EC220E 315233 - SWING DRIVE



Sample No: VCP429273

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

Job No: 24534

SAMPI F	INFORMATION	1		
Sample Number		VCP429273	 	
Sample Date		29 Nov 2023	 	
Machine Hours		612	 	
Oil Hours		500	 	
Oil Changed		N/A	 	
Sample Status		ATTENTION	 	
Sample Status		ATTENTION	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<u> </u>	 	
VOLVO	IINATION			
	MINATION			
Water	%	NEG	 	
Silicon	ppm	13	 	
Sodium	ppm	■4	 	
Potassium	ppm	■3	 	
WEAR M	AFTAI S			
_		=00		
Iron	ppm	■88	 	
Copper	ppm	□ 18	 	
Lead	ppm	0	 	
Tin	ppm	■0	 	
Aluminum	ppm	■<1	 	
Chromium	ppm	1	 	
Molybdenum	ppm	- <1	 	
Nickel	ppm	■0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	
VOLVO			 	
ADDITIV	ZES			
Calcium	ppm	<u> 47</u>	 	
Magnesium	ppm	<u>_</u> 4,	 	
Zinc	ppm	<u> </u>	 	
Phosphorus	ppm	<u>△</u> 320	 	
Barium	ppm	■ 0	 	
Boron	ppm	<u> </u>	 	
DOTOTT	ppiii	_		



218 - ASCENDUM MACHINERY INC - N. CHARLESTON 7235 CROSS COUNTRY RD. NORTH CHARLESTON, SC US 29418 Contact: MATT MITCHAM matt.mitcham@ascendummachinery.com T: F: (843)414-1129

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is higher than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot:VOLVO3387Unique No:10777987Signed:Don BaldridgeReport Date:10 Dec 2023



CONSTRUCTION EQUIPMENT





GRAPHS

