CONSTRUCTION EQUIPMENT SW1027074 LKQ VOLVO L90H 624179 - REAR AXLE



Sample No: VCP441353 **Oil Type:** VOLVO WB 102 Job No: SW1027074 LKQ

VOLVO

SAMPLE INFORMATION

-	VCP441353	VCP281388		
	30 Nov 2023	04 Aug 2020		
	10139	2008		
	0	0		
	N/A	Changed		
	NORMAL	NORMAL		
ITION				
cSt	39.5	40.5		
NATION				
%	NEG	NEG		
ppm	16	14		
ppm	7	2		
ppm	4	2		
TALS				
ppm	105	68		
ppm	37	133		
ppm	□ <1	1		
ppm	5	12		
ppm	1	< 1		
ppm	3	3		
ppm	1	4		
	TION cSt NATION % ppm ppm ppm ppm ppm ppm ppm ppm ppm p	VCP441353 30 Nov 2023 10139 0 N/A NORMAL	VCP441353 VCP281388 30 Nov 2023 04 Aug 2020 10139 2008 0 0 N/A Changed NORMAL NORMAL	VCP441353 VCP281388 30 Nov 2023 04 Aug 2020 10139 2008 0 0 NA Changed NORMAL NORMAL TION cSt 39.5 40.5 NATION % NEG NEG ppm 16 14 ppm 7 2 ppm 37 133 ppm 105 68 ppm 5 12 ppm 3 3

0

0

7

0

4105

1346

1266

123

9

0

2



ARNOLD MACHINERY COMPANY

4323 EAST WINSLOW AVENUE PHOENIX, AZ US 85040 Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com T: F: (602)414-1904

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:	VOLVO6174
Unique No:	10777990
Signed:	Wes Davis
Report Date:	09 Dec 2023

1

<1

0

<1

3792

1580

1307

8

0 🔲

127

5

ppm

ADDITIVES

Nickel

Silver

Titanium

Manganese

Vanadium

Calcium

Zinc

Barium

Boron

Magnesium

Phosphorus

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO

