



CONSTRUCTION EQUIPMENT

VOLVO L60H 622906 - REAR AXLE



Sample No: VCP413550
Oil Type: NOT GIVEN
Job No:



SAMPLE INFORMATION

Sample Number	VCP413550	---	---	---
Sample Date	01 Dec 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: SHAWN NORTHCRAFT
 shawn.northcraft@altg.com
 T: (904)737-6000
 F: (904)737-1260



OIL CONDITION

Visc @ 40°C	cSt	■ 39.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 1	---	---	---
Sodium	ppm	■ 3	---	---	---
Potassium	ppm	■ 5	---	---	---



WEAR METALS

Iron	ppm	■ 4	---	---	---
Copper	ppm	■ 2	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	0	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	0	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	84	---	---	---
Magnesium	ppm	0	---	---	---
Zinc	ppm	389	---	---	---
Phosphorus	ppm	310	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	<1	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0092
Unique No: 10777992
Signed: Don Baldrige
Report Date: 10 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

