



CONSTRUCTION EQUIPMENT

LKQ VOLVO L60H 622998 - TRANSMISSION



Sample No: VCP440776
Oil Type: DIESEL ENGINE OIL SAE 15W40
Job No: LKQ



SAMPLE INFORMATION

Sample Number	VCP440776	---	---	---
Sample Date	28 Nov 2023	---	---	---
Machine Hours	1027	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	ATTENTION	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	▲ 28.2	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 7	---	---	---
Sodium	ppm	■ 4	---	---	---
Potassium	ppm	■ 2	---	---	---



WEAR METALS

Iron	ppm	■ 94	---	---	---
Copper	ppm	■ 7	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 10	---	---	---
Vanadium	ppm	■ 0	---	---	---



ADDITIVES

Calcium	ppm	▲ 70	---	---	---
Magnesium	ppm	■ 2	---	---	---
Zinc	ppm	▲ 28	---	---	---
Phosphorus	ppm	▲ 187	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 64	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The fluid viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

Depot: VOLVO0093
Unique No: 10778032
Signed: Don Baldrige
Report Date: 10 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

