

CONSTRUCTION EQUIPMENT

1739 VOLVO EC750 310137 - REAR RIGHT FINAL DRIVE

Sample No: VCP434783

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

Job No: 621739

SAMPLE INFORMATION					
Sample Number		VCP434783	VCP349224	VCP259848	
Sample Date		30 Nov 2023	01 Mar 2022	25 Sep 2019	
Machine Hours		6059	4065	528	
Oil Hours		1000	0	0	
Oil Changed		Changed	Changed	Changed	
Sample Status		SEVERE	SEVERE	NORMAL	
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			
VOLVO	NITION				
OIL CONE					
Visc @ 40°C	cSt	138	95.9	167	
VOLVO					
CONTAMINATION					
Water	%	NEG	NEG	NEG	
Silicon	ppm	491	448	6	
Sodium	ppm	12	■ 8	■0	
Potassium	ppm	47	■29	2	
WEAR METALS					
_		•			
Iron	ppm	<u> 1301</u>	635	100	
Copper	ppm	2	1	- <1	
Lead	ppm	0	<1	- <1	
Tin	ppm	0	<1	= <1	
Aluminum	ppm	<u>128</u>	96	<1	
Chromium	ppm	9	7	2	
Molybdenum	ppm	2	18	0	
Nickel	ppm	<u> </u>	0	<1	
Titanium	ppm	7	4	<1	
Silver	ppm	0	0	0	
Manganese	ppm	12	8	2	
Vanadium	ppm	<1	<1	0	
VOLVO					
ADDITIV	ES				
Calcium	ppm	■230	■830	1 8	
Magnesium	ppm	■90	228	0	
Zinc	ppm	■88	■389	1 1	
Phosphorus	ppm	1781	1437	■350	
Barium	ppm	0	0	1 3	
Boron	ppm	9 1	1 03	□0	



BLAZE CONSTRUCTION

5640 ST JEAN ST DETROIT, MI US 48213 Contact: DAVE WARD dward@blazecontracting.net T: (248)632-2317 F:

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. We recommend an early resample to monitor this condition. Gear wear is indicated. Elemental levels of silicon (Si) and aluminum (Al) indicate aluminasilicate (coarse dirt) ingress. The oil is no longer serviceable due to the presence of contaminants.

Depot:BLADETUnique No:10779561Signed:Don BaldridgeReport Date:12 Dec 2023



CONSTRUCTION EQUIPMENT





