



# CONSTRUCTION EQUIPMENT

634767 INT TILE VOLVO L45H 4222098 - FRONT AXLE



**Sample No:** VCP431590  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 634767 INT TILE



**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## SAMPLE INFORMATION

Sample Number	VCP431590	---	---	---
Sample Date	30 Nov 2023	---	---	---
Machine Hours	2195	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	▲ 63.0	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 12	---	---	---
Sodium	ppm	■ 12	---	---	---
Potassium	ppm	■ 10	---	---	---



## WEAR METALS

Iron	ppm	■ 72	---	---	---
Copper	ppm	■ 5	---	---	---
Lead	ppm	■ 2	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ 1	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ 4	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 3	---	---	---
Vanadium	ppm	<1	---	---	---



## ADDITIVES

Calcium	ppm	▲ 2340	---	---	---
Magnesium	ppm	■ 0	---	---	---
Zinc	ppm	▲ 1115	---	---	---
Phosphorus	ppm	■ 836	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 86	---	---	---

## Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

**Depot:** VOLVO0096  
**Unique No:** 10780781  
**Signed:** Sean Felton  
**Report Date:** 14 Dec 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

