



# CONSTRUCTION EQUIPMENT

SWO-068173 APAC VOLVO L150H 6814 - COOLANT



**Sample No:** VCP447554  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** SWO-068173 APAC



## SAMPLE INFORMATION

Sample Number	<b>VCP447554</b>	VCP354666	VCP303044	VCP288650
Sample Date	<b>10 Dec 2023</b>	12 Jun 2022	08 Mar 2021	06 Oct 2020
Machine Hours	<b>7105</b>	5188	2676	3920
Sample Status	<b>NORMAL</b>	NORMAL	NORMAL	NORMAL

**COWIN EQUIPMENT COMPANY INC**  
1501 HWY 78 EAST  
OXFORD, AL  
US 36203  
Contact: STEVE CAMPBELL  
stcampbell@cowin.com  
T: (256)832-5053  
F: (256)831-4295



## COOLANT CONDITION

pH	Scale 0-14	<b>7.25</b>	7.20	7.20	7.45
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	<b>NT</b>	0	NT	0
Percentage Glycol	%	<b>46.6</b>	46.4	46	46
Freezing Point	°C	<b>-26</b>	-26	-29	-28

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



## CONTAMINATION

Coolant Appearance	<b>normal</b>	normal	normal	normal
Coolant Color	<b>Yllow</b>	Yllow	Green	Yllow

**Depot:** COWOXF  
**Unique No:** 10789198  
**Signed:** Jonathan Hester  
**Report Date:** 21 Dec 2023




# CONSTRUCTION EQUIPMENT




## VOLVO GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

