

CONSTRUCTION EQUIPMENT

VOLVO A45GFS A45GFS 352240 - DIESEL ENGINE

Sample No: VCP440618 Oil Type: **NOT GIVEN** Job No: 405584 P&M

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP440618	VCP0007656	
Sample Date		05 Dec 2023	19 May 2023	
Machine Hours		6561	6177	
Oil Hours		0	6177	
Oil Changed		Changed	N/A	
Sample Status		NORMAL	NORMAL	
OIL CONDI	TION			
Visc @ 100°C	cSt	12.4	12.9	
Base Number (BN)	mg KOH/g	7.9	■9.5	
Oxidation (PA)	%	65	57	
CONTAMI	NATION			
Water	%	NEG	NEG	
Soot %	%	■ 0.4	□ 0.1	
Nitration (PA)	%	83	53	
Sulfation (PA)	%	56	51	
Glycol	%	NEG	NEG	
Fuel	%	■ 0.4	<1.0	
Silicon	ppm	4	4	
Sodium	ppm	2	3	
Potassium	ppm	1	2	
WEAR ME	TALS			
Iron	ppm	7	3	
Copper	ppm	2	- <1	
Lead	ppm	0	< 1	
Tin	ppm	■ <1	0	
Aluminum	ppm	2	0	
Chromium	ppm	■ <1	0	
Molybdenum	ppm	■ 63	6 3	
Nickel	ppm	■<1	0	
Titanium	ppm	<1	- <1	
Silver	ppm	■ 0	0	
Manganese	ppm	<1	- <1	
Vanadium	ppm	0	0	
ADDITIVE	2			
Calcium	ppm	1129	■1154	
Magnesium	ppm	■914	972	
Zinc	ppm	1295	1284	
Phosphorus	ppm	1057	■1023	
Barium	ppm	0	0	
_		_		



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 30 Diesel Engine Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 10789221 Signed: Wes Davis Report Date: 19 Dec 2023

Submitted By: TECHNICIAN ACCOUNT

ppm

Boron



CONSTRUCTION EQUIPMENT





