



CONSTRUCTION EQUIPMENT

VOLVO L70H 624987 - FRONT AXLE



Sample No: VCP431705
Oil Type: VOLVO WET BRAKE TRANSAXLE OIL
Job No:



SAMPLE INFORMATION

Sample Number	VCP431705	---	---	---
Sample Date	12 Dec 2023	---	---	---
Machine Hours	1439	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



OIL CONDITION

Visc @ 40°C	cSt	█ 41.0	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 16	---	---	---
Sodium	ppm	█ 10	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 46	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 14	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 8	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 4345	---	---	---
Magnesium	ppm	█ 5	---	---	---
Zinc	ppm	█ 1651	---	---	---
Phosphorus	ppm	█ 1454	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 129	---	---	---

Depot: VOLVO0090
Unique No: 10790656
Signed: Wes Davis
Report Date: 15 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

