



CONSTRUCTION EQUIPMENT

VOLVO L70H 624987 - TRANSMISSION (AUTO)



Sample No: VCP431930
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



SAMPLE INFORMATION

Sample Number	VCP431930	---	---	---
Sample Date	12 Dec 2023	---	---	---
Machine Hours	1439	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	ABNORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



OIL CONDITION

Visc @ 40°C	cSt	█ 27.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ <1	---	---	---

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	▲ 178	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 9	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 69	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 14	---	---	---
Phosphorus	ppm	█ 244	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 72	---	---	---

Depot: VOLVO0090
Unique No: 10790693
Signed: Jonathan Hester
Report Date: 19 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

