



# CONSTRUCTION EQUIPMENT

## VOLVO L90H 625855 - TRANSMISSION (AUTO)



**Sample No:** VCP421021  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP421021	---	---	---
Sample Date	11 Dec 2023	---	---	---
Machine Hours	2920	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY**  
 5151 DR MARTIN LUTHER KING BLVD  
 FORT MYERS, FL  
 US 33905  
 Contact: TODD LARK  
 tlark@altaequipfl.com  
 T:  
 F: (239)481-3302



### OIL CONDITION

Visc @ 40°C	cSt	█ 27.4	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ <1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 132	---	---	---
Copper	ppm	█ 11	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 8	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	75	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 22	---	---	---
Phosphorus	ppm	█ 189	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 61	---	---	---

**Depot:** VOLVO0090  
**Unique No:** 10790694  
**Signed:** Jonathan Hester  
**Report Date:** 19 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

