



# CONSTRUCTION EQUIPMENT

ALTA RENTS VOLVO L70H 624830 - TRANSMISSION (AUTO)



**Sample No:** VCP440736  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** ALTA RENTS



## SAMPLE INFORMATION

Sample Number	VCP440736	---	---	---
Sample Date	06 Dec 2023	---	---	---
Machine Hours	1366	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	■ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 8	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ <1	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 129	---	---	---
Copper	ppm	■ 7	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ 0	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 6	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	80	---	---	---
Magnesium	ppm	■ 0	---	---	---
Zinc	ppm	■ 27	---	---	---
Phosphorus	ppm	■ 204	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 66	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 10790695  
**Signed:** Jonathan Hester  
**Report Date:** 19 Dec 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

