

CONSTRUCTION EQUIPMENT REPUBLIC SERVICES TOYOTA 62680 - DIESEL ENGINE



Sample No: VCP441686

Oil Type: MOBIL DELVAC 1300 SUPER 10W30

Job No: REPUBLIC SERVICES

SAMPLE INFORMATION					
	AF URMA HUN		_		_
Sample Number		VCP441686			
Sample Date		07 Dec 2023			
Machine Hours		0			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIT CONDI.	TION				
Visc @ 100°C	cSt	■9.7			
Base Number (BN)	mg KOH/g	■ 5.0			
Oxidation (PA)	%	54			
VOLVO					
CONTAMIN	IATIUN				
Water	%	NEG			
Soot %	%	■ 0.1			
Nitration (PA)	%	81			
Sulfation (PA)	%	67			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	13			
Sodium	ppm	8			
Potassium	ppm	2			
	PP				
VOLVO					
WEAR ME	IALS				
Iron	ppm	■25			
Copper	ppm	2			
Lead	ppm	■ 0			
Tin	ppm				
Aluminum	ppm	■7			
Chromium	ppm	■8			
Molybdenum	ppm	■55			
Nickel	ppm	■0			
Titanium	ppm	<1			
Silver	ppm	■ 0			
Manganese	ppm	■<1			
Vanadium	ppm	0			
- Alled all	PP'''	•			
ADDITIVES					
Calcium	ppm	1260			
Magnesium	ppm	484			
Zinc	ppm	■ 956			
Phosphorus	ppm	754			
	1- 1-1-1				



ARNOLD MACHINERY COMPANY

2975 WEST 2100 SOUTH SALT LAKE CITY, UT US 84119 Contact: TJ LARK tlark@arnoldmachinery.com T: (801)972-4000 F: (801)975-9434

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot: VOLVO8770 **Unique No:** 10792832 Signed: Wes Davis Report Date: 19 Dec 2023

Contact/Location: TJ LARK - VOLVO8770

ppm

ppm

Barium

Boron

0

58



CONSTRUCTION EQUIPMENT





