
**CONSTRUCTION EQUIPMENT** SPM634758

SENNEBOGEN 825ME 825.0.3752 - REAR LEFT FINAL DRI

Sample No:	VCP428524
Oil Type:	GEAR OIL SAE 80W90
Job No:	SPM634758

VOLVO

## SAMPLE INFORMATION VCP428524 Sample Number Sample Date 29 Nov 2023 Machine Hours 2519 Oil Hours 0 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 144 CONTAMINATION Water % NEG Silicon 2 ppm Sodium 2 ppm Potassium ppm 12 WEAR METALS Iron ppm 2 Copper ppm ■ <1 Lead ppm **||** <1 Tin ppm 0 🔲 Aluminum ppm 2 Chromium 0 🔲 ppm



01 **ADDITIVES** Calcium 48 ppm Magnesium 12 ppm Zinc ppm 21 Phosphorus 204 ppm Barium 0 🔲 ppm 0 Boron ppm



## LEMONT SCRAP

16229 NEW AVE. LEMONT, IL US 60432 Contact: Service Manager

T: F:

## Diagnosis


Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: LEMLEMVC Unique No: 10793390 Signed: Jonathan Hester **Report Date:** 20 Dec 2023

## **CONSTRUCTION EQUIPMENT**



VOLVO



-----