
**CONSTRUCTION EQUIPMENT** SPM634758

SENNEBOGEN 825ME 825.0.3752 - FRONT LEFT FINAL

| Sample No: | VCP428527          |
|------------|--------------------|
| Oil Type:  | GEAR OIL SAE 80W90 |
| Job No:    | SPM634758          |

VOLVO

## SAMPLE INFORMATION VCP428527 Sample Number Sample Date 29 Nov 2023 Machine Hours 2519 Oil Hours 0 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 145 CONTAMINATION Water % NEG Silicon **||** <1 ppm Sodium 1 🔲 ppm Potassium ppm 10 WEAR METALS Iron ppm 0 🔲 Copper ppm 0 Lead ppm 0 🔲 Tin ppm 0 🔲 Aluminum ppm 2 Chromium 0 🔲 ppm



01 **ADDITIVES** Calcium 23 ppm Magnesium 11 ppm Zinc ppm 12 Phosphorus 236 ppm Barium 0 🔲 ppm 0 Boron ppm



## LEMONT SCRAP

16229 NEW AVE. LEMONT, IL US 60432 Contact: Service Manager

T: F:

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot: LEMLEMVC Unique No: 10793396 Signed: Jonathan Hester **Report Date:** 20 Dec 2023

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: LEMLEMVC [WUSCAR] 06038167 (Generated: 12/20/2023 18:00:40) Rev: 1

Contact/Location: Service Manager - LEMLEMVC