CONSTRUCTION EQUIPMENT SPM634758 SENNEBOGEN 825ME 825.0.3

1634758 SENNEBOGEN 825ME 825.0.3752 - FRONT RIGHT FINAL DRI

Sample No:	VCP428523
Oil Type:	GEAR OIL SAE 80W90
Job No:	SPM634758

VOLVO

SAMPLE INFORMATION VCP428523 Sample Number Sample Date 29 Nov 2023 Machine Hours 2519 Oil Hours 0 Oil Changed Not Changd NORMAL Sample Status T: **OIL CONDITION** F: Visc @ 40°C cSt 143 CONTAMINATION Water % NEG Silicon ppm 1 Sodium 1 🔲 ppm Potassium ppm 9 WEAR METALS Iron ppm 0 🔲 Copper ppm 0 Lead ppm 0 🔲 Tin ppm 0 🔲 Aluminum ppm 2 Chromium 0 🔲 ppm Molybdenum ppm 0 Nickel 0 ppm Titanium 0 ppm Silver 0 ppm

Manganese Vanadium ppm

ppm

0

0

01 **ADDITIVES** Calcium 23 ppm Magnesium 11 ppm Zinc ppm 13 Phosphorus 242 ppm Barium 0 🔲 ppm 0 Boron ppm



LEMONT SCRAP

16229 NEW AVE. LEMONT, IL US 60432 Contact: Service Manager

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:LEMLEMVCUnique No:10793400Signed:Jonathan HesterReport Date:20 Dec 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: LEMLEMVC [WUSCAR] 06038171 (Generated: 12/20/2023 18:00:47) Rev: 1

Contact/Location: Service Manager - LEMLEMVC