



# CONSTRUCTION EQUIPMENT

JMH VOLVO A40G 353130 - REAR AXLE



**Sample No:** VCP435566  
**Oil Type:** NOT GIVEN  
**Job No:** JMH



## SAMPLE INFORMATION

Sample Number	VCP435566	---	---	---
Sample Date	14 Dec 2023	---	---	---
Machine Hours	2194	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	■ 52.0	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 1	---	---	---
Sodium	ppm	■ 3	---	---	---
Potassium	ppm	■ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	■ 54	---	---	---
Copper	ppm	■ <1	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	<1	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	3	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	5	---	---	---
Magnesium	ppm	0	---	---	---
Zinc	ppm	0	---	---	---
Phosphorus	ppm	2388	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	270	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 10793431  
**Signed:** Don Baldrige  
**Report Date:** 20 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

