



CONSTRUCTION EQUIPMENT

SWO-068207 VOLVO A60H 350190 - REAR AXLE



Sample No: VCP447569
Oil Type: NOT GIVEN
Job No: SWO-068207



SAMPLE INFORMATION

Sample Number	VCP447569	VCP433968	VCP395234	VCP388112
Sample Date	12 Dec 2023	05 Sep 2023	05 May 2023	19 Jan 2023
Machine Hours	3131	2618	2128	1651
Oil Hours	0	0	0	0
Oil Changed	Not Changd	Not Changd	Not Changd	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SAIIA CONSTRUCTION LLC
 4400 LEWISBURG RD
 BIRMINGHAM, AL
 US 35207
 Contact: STEPHANI BRITTON
 sbritton@saiia.com;doug.bogart@wearcheck.com
 T: (205)943-2268
 F: (205)943-2269



OIL CONDITION

Visc @ 40°C	cSt	49.3	49.1	50.4	49.5
-------------	-----	-------------	------	------	------



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	3	2	2
Sodium	ppm	2	3	3	2
Potassium	ppm	1	3	3	3

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	81	102	121	62
Copper	ppm	<1	0	<1	<1
Lead	ppm	0	0	0	<1
Tin	ppm	0	0	<1	0
Aluminum	ppm	0	0	0	<1
Chromium	ppm	<1	2	2	1
Molybdenum	ppm	1	2	3	2
Nickel	ppm	0	<1	<1	<1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	4	6	6	4
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	319	335	337	307
Magnesium	ppm	<1	2	1	1
Zinc	ppm	145	144	146	147
Phosphorus	ppm	2287	2326	2402	2185
Barium	ppm	0	0	0	0
Boron	ppm	277	300	280	267

Depot: SAIBIR
Unique No: 10793446
Signed: Don Baldrige
Report Date: 20 Dec 2023

VOLVO GRAPHS

