



# CONSTRUCTION EQUIPMENT

## SW27529 VOLVO ECR145E 314542 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP06040840  
**Oil Type:** NOT GIVEN  
**Job No:** SW27529



### SAMPLE INFORMATION

Sample Number	VCP06040840	---	---	---
Sample Date	13 Dec 2023	---	---	---
Machine Hours	2127	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

**ARNOLD MACHINERY COMPANY**  
 3330 NORTH YELLOWSTONE HIGHWAY  
 IDAHO FALLS, ID  
 US 83401  
 Contact: JASON MERRILL  
 jmerrill@arnoldmachinery.com  
 T: (208)523-0822  
 F: (208)523-9918



### OIL CONDITION

Visc @ 40°C	cSt	█ 185	---	---	---
-------------	-----	-------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 1	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 150	---	---	---
Copper	ppm	█ 2	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 4	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	2	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	2	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	40	---	---	---
Magnesium	ppm	2	---	---	---
Zinc	ppm	17	---	---	---
Phosphorus	ppm	328	---	---	---
Barium	ppm	0	---	---	---
Boron	ppm	11	---	---	---

**Depot:** VOLVO0077  
**Unique No:** 10796069  
**Signed:** Jonathan Hester  
**Report Date:** 22 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

