



CONSTRUCTION EQUIPMENT

SW-26700-2 EVERGREEN VOLVO L110H 631790 - FRONT AXLE



Sample No: VCP435862
Oil Type: VOLVO WB 102
Job No: SW-26700-2 EVERGREEN



SAMPLE INFORMATION

Sample Number	VCP435862	VCP337851	VCP289524	---
Sample Date	14 Dec 2023	15 Sep 2022	21 Jul 2021	---
Machine Hours	6006	4054	1990	---
Oil Hours	2000	2000	1000	---
Oil Changed	Changed	Changed	Changed	---
Sample Status	NORMAL	NORMAL	NORMAL	---

ARNOLD MACHINERY COMPANY
 2975 WEST 2100 SOUTH
 SALT LAKE CITY, UT
 US 84119
 Contact: TONY PAYAN
 tpayan@arnoldmachinery.com
 T: (801)972-4000
 F: (801)975-9434



OIL CONDITION

Visc @ 40°C	cSt	47.9	42.0	40.3	---
-------------	-----	-------------	------	------	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	---
Silicon	ppm	9	15	12	---
Sodium	ppm	1	10	9	---
Potassium	ppm	0	0	<1	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	106	139	93	---
Copper	ppm	2	<1	<1	---
Lead	ppm	1	<1	<1	---
Tin	ppm	0	0	<1	---
Aluminum	ppm	<1	1	1	---
Chromium	ppm	2	3	2	---
Molybdenum	ppm	2	2	2	---
Nickel	ppm	<1	0	0	---
Titanium	ppm	0	<1	<1	---
Silver	ppm	0	0	0	---
Manganese	ppm	2	4	3	---
Vanadium	ppm	<1	0	0	---



ADDITIVES

Calcium	ppm	2938	4162	3831	---
Magnesium	ppm	1	17	15	---
Zinc	ppm	1220	1653	1560	---
Phosphorus	ppm	1051	1303	1261	---
Barium	ppm	0	0	0	---
Boron	ppm	36	124	166	---

Depot: VOLVO8770
Unique No: 10796072
Signed: Wes Davis
Report Date: 21 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

