

CONSTRUCTION EQUIPMENT VOLVO A40G 352489 - COOLANT



Sample No: VCP434153

Oil Type:	VOLVO COOLANT VCS (YELLOW)
-----------	----------------------------

Job No:

SAMPLE II	NFORMATION					
Sample Number	-	VCP434153				
Sample Date		13 Dec 2023				
Machine Hours		6270				
Sample Status		NORMAL				
COOLANT	CONDITION					
рН	Scale 0-14	7.15				
Reserve Alkalinity	Scale 0-20					
Nitrites	ppm	NT				
Percentage Glycol	%	41.6				
Freezing Point	°C	-15				
CONTAMINATION						
Coolant Appearance		normal				
Coolant Color		Yllow				



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com T: F: (239)481-3302

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

 Depot:
 VOLVO090

 Unique No:
 10796215

 Signed:
 Jonathan Hester

 Report Date:
 22 Dec 2023

CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO

