

CONSTRUCTION EQUIPMENT VOLVO EC250EL 314172 - DIESEL ENGINE



Sample No: VCP434046

Oil Type: VALVOLINE 15W40

Job No:

VOLVO				
SAMPLE II	NFORMATION			
Sample Number	-	VCP434046	VCP364628	
Sample Date		16 Dec 2023	02 Oct 2023	
Machine Hours		2526	2232	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CONDI	TION			
Visc @ 100°C	cSt	12.3	12.8	
Base Number (BN)		7.2	9.0	
Oxidation (PA)	mg KOH/g %	38	82	
Oxidation (PA)	70	30	02	
VOLVO				
CONTAMIN	NATION			
Water	%	NEG	NEG	
Soot %	%	■ 0.1	■0.2	
Nitration (PA)	%	52	59	
Sulfation (PA)	%	45	59	
Glycol	%	NEG	NEG	
Fuel	%	■ 0.3	<1.0	
Silicon	ppm	10	1 9	
Sodium	ppm	■ 0	3	
Potassium	ppm	4	1 2	
WEAR ME	7147			
_				
Iron	ppm	6	18	
Copper	ppm	■ <1	4	
Lead Tin	ppm	0	0	
	ppm			
Aluminum Chromium	ppm	■ 9	21	
	ppm	■ < 1 ■ 35	4 2	
Molybdenum Nickel	ppm	35	3	
Titanium	ppm	■ 0	3 <1	
Silver	ppm	0	0	
	ppm	■ <1	□ <1	
Manganese Vanadium	ppm	0	0	
variaululii	ppm	U	U	
VOLVO				
ADDITIVE	2			
Calcium	ppm	1986	□1657	
Magnesium	ppm	138	472	
Zinc	ppm	976	1113	
Phosphorus	ppm	756	■912	
Barium	ppm	0	□0	
5		-40	-0.4	



CITY CARTING
221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS
tavins@citycart.net
T: (203)223-3885
F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.All component wear rates are normal. Fuel content negligible. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:CITMILCONUnique No:10796397Signed:Wes DavisReport Date:26 Dec 2023

Boron



CONSTRUCTION EQUIPMENT





