



CONSTRUCTION EQUIPMENT

VOLVO L150H 6989 - COOLANT



Sample No: VCP407072
Oil Type: NOT GIVEN
Job No:



SAMPLE INFORMATION

Sample Number	VCP407072	---	---	---
Sample Date	15 Dec 2023	---	---	---
Machine Hours	5961	---	---	---
Sample Status	NORMAL	---	---	---

CITY CARTING

221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS
tavins@citycart.net
T: (203)223-3885
F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.19	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 46.5	---	---	---
Freezing Point	°C	■ -26	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: CITMILCON
Unique No: 10802386
Signed: Jonathan Hester
Report Date: 26 Dec 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

