## CONSTRUCTION EQUIPMENT 319341 IAA VOLVO L90H 626972 - FRONT AXLE



Sample No:	VCP350625
Oil Type:	VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102
Job No:	319341 IAA

VOLVO

## SAMPLE INFORMATION VCP350625 Sample Number Sample Date 15 Dec 2023 **PACWEST MACHINERY** Machine Hours 1066 4030 EAST TRENT AVENUE Oil Hours 1066 SPOKANE, WA US 99202 Oil Changed N/A NORMAL Contact: SAM SICILIA Sample Status ssicilia@pacwestmachinery.com T: (509)954-5973 **OIL CONDITION** F: (509)534-5286 Visc @ 40°C cSt 41.14 Diagnosis CONTAMINATION Resample at the next service interval Water % NEG to monitor.All component wear rates Silicon 17 are normal. There is no indication of ppm any contamination in the oil. The Sodium 0 🔲 ppm condition of the oil is acceptable for Potassium ppm 2 the time in service. WEAR METALS Iron ppm 41 Copper ppm 1 Lead ppm 0 🔲 Tin ppm 0 🔲 Aluminum ppm 3 Chromium 2 ppm Molybdenum ppm 6 Nickel ■ <1 ppm Titanium <1 ppm Silver 0 ppm Manganese ppm 6 Vanadium ppm 0 01 **ADDITIVES** Calcium 4136 ppm Magnesium 10 ppm Zinc ppm 1679 Phosphorus 1332 ppm

 Depot:
 VOLVO1272

 Unique No:
 10803044

 Signed:
 Jonathan Hester

 Report Date:
 28 Dec 2023

0 🔲

144

ppm

ppm

Barium


Boron

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO1272 [WUSCAR] 06042436 (Generated: 12/28/2023 13:05:52) Rev: 1

Contact/Location: SAM SICILIA - VOLVO1272