



CONSTRUCTION EQUIPMENT

420619 MUSKEGON CC VOLVO L60H 622097 - COOLANT



Sample No: VCP407327
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 420619 MUSKEGON CC



SAMPLE INFORMATION

Sample Number	VCP407327	---	---	---
Sample Date	30 Nov 2023	---	---	---
Machine Hours	7643	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	7.54	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	---	---	---
Percentage Glycol	%	51.8	---	---	---
Freezing Point	°C	-38	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---



ALTA EQUIPMENT COMPANY- BYRON CENTER
 8840 BYRON COMMERCE DR SW
 BYRON CENTER, MI
 US 49315
 Contact: BRIAN RESER
 brian.reser@altaequipment.com
 T: (616)878-7450
 F: (616)878-7650

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO0046
Unique No: 10803134
Signed: Jonathan Hester
Report Date: 26 Dec 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity



Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

