



CONSTRUCTION EQUIPMENT

433110 STONE PLUS VOLVO L30G 3221516 - COOLANT



Sample No: VCP431578
Oil Type: NOT GIVEN
Job No: 433110 STONE PLUS



SAMPLE INFORMATION

Sample Number	VCP431578	VCP0006234	---	---
Sample Date	16 Dec 2023	21 Feb 2023	---	---
Machine Hours	5442	0	---	---
Sample Status	NORMAL	NORMAL	---	---

ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: SHAWN NORTHCRAFT
 shawn.northcraft@altg.com
 T: (904)737-6000
 F: (904)737-1260



COOLANT CONDITION

pH	Scale 0-14	7.53	8.51	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	---	---
Percentage Glycol	%	40.7	49.8	---	---
Freezing Point	°C	-13	-33	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	---	---
Coolant Color	Orange	Yllow	---	---

Depot: VOLVO0092
Unique No: 10804332
Signed: Jonathan Hester
Report Date: 29 Dec 2023



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

